

<b>INCIDENT / DEFECT REPORTS</b>	<b>DATE</b>	<b>ACTIONS</b>
Two fenders observed not securely attached in the Prince Philip Lock	01/10/2021	Fenders removed by Engineering team as precautionary measure
Oil spill caused by a burst hydraulic hose on fishing vessel	15/10/2021	Incident investigated and monitored.
A piece of timber was floating near to the hydraulic ram pit of the Prince Phillip lock	22/10/2021	Area inspected no signs of timber floating in the vicinity
<b>ACCIDENTS</b>	<b>DATE</b>	<b>ACTIONS</b>
None		
<b>NAVIGATIONAL</b>	<b>DATE</b>	<b>ACTIONS</b>
Packs of Timber being discharged from a cargo vessel fell into the canal	05/10/2021	Packs recovered and put shoreside
<b>EXERCISES/ TRAINING</b>	<b>DATE</b>	
Marine Dec Training	04 to 06/10/2021	
Man Overboard Drill	08/10/2021	
Communications Training	13/10/2021	
Shoreham Port Major Incident Exercise	21/10/2021	
Bridge Resource Management	25 to 26/10/2021	
<b>AUDITS/ INSPECTIONS / REVIEWS</b>	<b>DATE</b>	
SPA-Nav 16 Towing and Pushing leisure and small vessels with port craft other than the tug, Risk Assessment Review	14/10/2021	
SPA-NAV 05 - Use, control and management of locks, Risk Assessment Review	14/10/2021	
09 - Pilotage Manual- Review	14/10/2021	
East Arm Safety Inspection	14/10/2021	
Mooring Bollard inspection	15/10/2021	
Safety Briefing for Pilot Boat Transfer - Review	18/10/2021	
<b>MEETINGS / CONFERENCE CALLS</b>	<b>DATE</b>	
Merchant Navy Welfare Board	05/10/2021	
Port Security Officers Forum	08/10/2021	
Fisherman's Mission	13/10/2021	
All Colleagues Conversations	13/10/2021	
Marine Operations monthly meeting	20/10/2021	
Safety Improvement Team meeting	28/10/2021	
<b>HYDROGRAPHIC SURVEYS CONDUCTED DURING THE MONTH</b>		
<ul style="list-style-type: none"> <li>• Canal berths – ARC terminal, Brighton Terminal Bol. 36 to 59, BT Rombus, Fishersgate terminal East and RNR wharf.</li> <li>• Entrance -Breakwaters to Resonators</li> <li>• Power Station cold Water Intakes – Cooling water intake channel adjacent to the Pumphouse.</li> </ul>		

Julian Seaman.  
 Harbour Master