

INCIDENT / DEFECT REPORTS	DATE	ACTIONS
Non-UK leisure vessel entered lock without following correct UK entry procedures	05/09/2021	Vessel was refused berthing arrangements and returned to sea
Jet Ski manoeuvring within the river Adur	07/09/2021	Patrol vessel was tasked to the area but no Jet ski was observed.
Child fell from quayside establishment into the water	11/09/2021	Child recovered unharmed by parent. Matter under investigation.
Leisure vessel sunk on its berth	13/09/2021	Vessel was pumped out and re-floated by its owner
Leisure vessel sunk on its berth	20/09/2021	Vessel was recovered from the water by salvor.
ACCIDENTS	DATE	ACTIONS
None		
NAVIGATIONAL	DATE	ACTIONS
Loss of Main Engine whilst approaching the Lock	11/09/2021	Vessel brought to a controlled stop in the locks with ships lines and engine was restarted.
Vessel made contact with ISPS fencing	30/09/2021	Incident investigated
EXERCISES/ TRAINING	DATE	
Man Overboard – Pilot Cutter	04/09/2021	
Man Overboard – Tug	24/09/2021	
Man Overboard – Tug	29/09/2021	
PMSC Exercise - Communication Failure	30/09/2021	
International Ship & Port Security Exercise	30/09/2021	
AUDITS/ INSPECTIONS / REVIEWS	DATE	
DfT Port Security Inspection	01/09/2021	
Seasonal patrol meeting	02/09/2021	
Document Control Audit	08/09/2021	
Crewsaver Service / Audit	15/09/2021	
SCOP 12 Enforcement Handbook	16/09/2021	
Lock Area & Associated areas - Safety Inspection	20/09/2021	
SCOP 15 Shoreham Harbour Leisure Season Patrols	29/09/2021	
MEETINGS / CONFERENCE CALLS	DATE	
British Ports Association Marine Pilotage Group	02/09/2021	
British Ports Association Regional Ports meeting	07/09/2021	
Monthly Marine Team Meeting	11/09/2021	
Sussex Kelp Sediment Impact	14/09/2021	
Tug Master meeting	15/09/2021	
British Ports Association Coastal Shipping Seminar	15/09/2021	
Business Risk & safety meeting	22/09/2021	
Board meeting	23/09/2021	
Marine Team Meeting	28/09/2021	
SIT Monthly meeting	30/09/2021	
HYDROGRAPHIC SURVEYS CONDUCTED DURING THE MONTH		
<ul style="list-style-type: none"> • Canal berths – Inner Lay-By terminal and Inner Lay-By Slant. • West Arm Berths -Fisherman’s and New wharf. • West arm Channel – Mudflat C to Soldiers Point. 		

Julian Seaman.
 Harbour Master