

**RWE Renewables UK Limited  
Rampion Offshore Wind Farm  
Notice To Mariners**

**Issuer : Rampion Operations Engineer**

**Date of Issue:17-03-23**

**NTM no : NTM RAM-2023-001**

For enquiries on this Notice to Mariners please  
contact:

[rampion.controlroom@rwe.com](mailto:rampion.controlroom@rwe.com)

07816061968



To Owners, Ships Agents, Masters, Pilots and Fishermen. Please see the following:

- **Risk of cable exposure within the Rampion Wind Farm**

Following recent surveys within the Rampion Offshore Wind Farm, a significant number of array cable exposures are being reported.

Due to the mobile nature of the seabed within the wind farm boundary these cable exposures are subject to change and may develop in areas where there were none previously.

Mariners are reminded that array cable exposures are a known risk at Rampion Offshore Wind Farm – for further safety information refer to “*The Risks of Fishing Near Cables and Renewable Energy Structures*”, published on the KIS-ORCA website.

Please note that the standard safety rules apply when fishing in or near wind farms and associated cables. All mariners are requested to make themselves aware of their obligations for conducting activities over buried and protected cables under International and UK Cable (Sub-sea) Protection Legislation.

Further INFORMATION on the risks to fishing adjacent to subsea cables can be found in Weblinks:

<https://kis-orca.org/>

<https://www.seafish.org/article/kingfisher-bulletins>

- **Distribution:**

As per Rampion Notices To Mariners Distribution List. Please feel free to share the information.