

Notice to Mariners

Rampion Offshore Wind Farm

Date of Issue: 26/11/2018
Notice Expires: 30/12/2018

Dear Owners, Ships Agents, Masters, Pilots and Fishermen,

Re: Rampion Offshore Wind Farm - EON-NTM-00125- CR3 &CR4 Export Cable Burial

Please be advised that the vessel Bravenes will be conducting burial operations to both export cables. Operations are planned to commence the second week in December 2018 and is due to last approx. 2 weeks weather permitting. The vessel will be operating from KP2.0 to the offshore substation.



Vessel: Bravenes
Draught: 8m
Length x Breadth: 154.4m x 28m
Gross Tonnage: 15500
Speed recorded (Max / Average): 12/9.8knots
Call Sign: PDCF
IMO: 975600
MMSI: 244860916
Flag: Netherlands (NL)

Mariners are advised to give the vessels a wide berth as the vessels will be restricted in manoeuvrability whilst carrying out operations.

All vessels are requested to remain a minimum safe distance of 500m from the vessels during operations and whilst they are on location.

Vessels will be monitoring channel 16 VHF and the project P1 channel

Please be aware that there remains exposed export cables on the sea bed

Interaction between fishing gears (OR anchors) and the export cables could also cause damage to the export cables themselves.

All commercial/recreational fishing vessels deploying any form of demersal fishing gears (trawls/shellfish dredgers etc.) or fixed fishing gears (pots, traps, nets etc) and any vessel's anchors should ensure that:

No such Gears, including anchors, come within the vicinity of the exposed/shallow buried cables

Mobile or towed demersal fishing gears (trawls, shellfish dredgers etc) including anchors, DO NOT come within the vicinity of the cables

Further information on the hazards of fishing adjacent to subsea cables can be found in:

- KIS-ORCA/Seafish document 'Kingfisher Awareness Chart, January 2016, English Channel' and in the attached chart

Weblinks: www.kis-orca.eu & http://www.kis-orca.eu/media/9292/2016%20English%20Channel_LRes.pdf

Notice to Mariners

Rampion Offshore Wind Farm

Date of Issue: 26/11/2018
 Notice Expires: 30/12/2018

Below Coordinates of Export cables.

CR 4 Coordinates

Latitude	Longitude	KP
50° 49.0347' N	0° 20.1759' W	0.000
50° 48.8174' N	0° 20.0679' W	0.422
50° 48.499' N	0° 19.9179' W	1.038
50° 47.5073' N	0° 19.2754' W	3.026
50° 46.9104' N	0° 19.0408' W	4.167
50° 46.8624' N	0° 19.028' W	4.257
50° 46.6346' N	0° 18.9954' W	4.681
50° 46.5865' N	0° 18.9951' W	4.770
50° 46.0698' N	0° 19.0621' W	5.732
50° 45.4367' N	0° 19.1944' W	6.916
50° 45.3316' N	0° 19.2183' W	7.113
50° 45.2744' N	0° 19.2241' W	7.219
50° 45.1798' N	0° 19.222' W	7.394
50° 45.0737' N	0° 19.1969' W	7.593
50° 44.4019' N	0° 18.9836' W	8.864
50° 44.2304' N	0° 18.939' W	9.186
50° 44.011' N	0° 18.8819' W	9.598
50° 43.7299' N	0° 18.7794' W	10.133
50° 43.441' N	0° 18.6499' W	10.690
50° 43.2979' N	0° 18.5716' W	10.971
50° 43.2454' N	0° 18.5349' W	11.078
50° 43.1797' N	0° 18.4776' W	11.217
50° 43.1319' N	0° 18.4271' W	11.324
50° 42.958' N	0° 18.2059' W	11.738
50° 42.7875' N	0° 17.9298' W	12.191
50° 42.3833' N	0° 17.1555' W	13.372
50° 42.2907' N	0° 16.9781' W	13.642
50° 41.9023' N	0° 16.2441' W	14.767
50° 41.796' N	0° 16.0069' W	15.109
50° 41.6474' N	0° 15.666' W	15.596
50° 41.6235' N	0° 15.6358' W	15.653
50° 41.5764' N	0° 15.5982' W	15.751

This is CR3 east cable RPL (CR2 replacement)

KP	WGS84 Latitude	WGS84 Longitude
0.000	50°49.0411'N	0°20.1492'W
0.006	50°49.0384'N	0°20.1472'W
0.401	50°48.8450'N	0°20.0043'W
1.019	50°48.5436'N	0°19.7817'W
3.097	50°47.5283'N	0°19.0324'W
4.003	50°47.0635'N	0°18.7953'W
4.505	50°46.7967'N	0°18.7217'W
4.757	50°46.6611'N	0°18.7071'W
5.759	50°46.1220'N	0°18.7677'W
7.114	50°45.4019'N	0°18.9671'W
7.222	50°45.3444'N	0°18.9758'W
7.321	50°45.2910'N	0°18.9770'W
7.439	50°45.2273'N	0°18.9702'W
10.026	50°43.8559'N	0°18.5656'W
10.633	50°43.5372'N	0°18.4469'W
10.884	50°43.4091'N	0°18.3785'W
11.055	50°43.3249'N	0°18.3183'W
11.214	50°43.2519'N	0°18.2483'W
11.313	50°43.2087'N	0°18.1987'W
11.443	50°43.1551'N	0°18.1270'W
11.704	50°43.0495'N	0°17.9807'W
11.949	50°42.9493'N	0°17.8447'W
12.083	50°42.8969'N	0°17.7662'W
12.146	50°42.8475'N	0°17.6541'W
12.248	50°42.8757'N	0°17.7250'W
13.450	50°41.9365'N	0°15.9714'W
14.848	50°41.7608'N	0°15.6987'W
15.306	50°41.7048'N	0°15.6218'W
15.444	50°41.7048'N	0°15.6218'W
15.468	50°41.6938'N	0°15.6095'W
15.486	50°41.6857'N	0°15.6021'W
15.511	50°41.6733'N	0°15.5939'W
15.536	50°41.6603'N	0°15.5884'W
15.561	50°41.6469'N	0°15.5855'W
15.586	50°41.6334'N	0°15.5854'W
15.691	50°41.5770'N	0°15.5934'W

Notice to Mariners

Rampion Offshore Wind Farm

Date of Issue: 26/11/2018
Notice Expires: 30/12/2018

Mark Brown

Offshore Site Manager

Tel: +44 (0) 7491 057 121

Email: mark.brown@eon.com

Gordon Bain

Lead Marine Coordinator

Tel: +44 (0) 7816 648 082

Email: leadmc@rampionoffshore.com

Duty Marine Coordinator

Tel: +44 (0) 7557 942 945

Email: traffic@rampionoffshore.com

Alex Winrow-Giffin

Brown & May Fisheries Liaison

Tel: +44 (0) 7760 160 039

Email: alex@brownmay.com